

Federal Energy Act Report

October 1, 2015 thru September 30, 2016

(Public Record Posted Date: December 2, 2016)

General Information:

Total Number of Active UST Facilities: **6,836**
 Total Number of Active/Inactive USTs: **19,087**

Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,503**
 Percent of UST Facilities in SOC Compliance: **62**

Note:

Facility and tank information is based on onsite inspections of all active regulated UST facilities and covers all active/inactive tanks at those facilities. Active regulated Illinois UST facilities are inspected on a two year cycle. Onsite inspections measure compliance against Illinois UST requirements at 41 Illinois Administrative Code Parts 174, 175, 176 & 177 and federal UST regulations at 40 CFR Part 280.

Summary Information For Releases:

Number of Confirmed UST Releases: **321**

Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	
Tank	162	50.5	0	0.0	3	0.9	3	0.9	109	34.0	0	0.0	0	0.0	47	14.6
Piping	22	6.9	0	0.0	0	0.0	0	0.0	10	3.1	0	0.0	0	0.0	12	3.7
Dispenser	3	0.9	0	0.0	0	0.0	1	0.3	1	0.3	0	0.0	0	0.0	1	0.3
Submersible (STP)	2	0.6	0	0.0	0	0.0	0	0.0	2	0.6	0	0.0	0	0.0	0	0.0
Delivery Problem	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Unknown	132	41.1	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	132	41.1
Other	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Totals	321	100.0	0	0.0	3	0.9	4	1.2	122	38.0	0	0.0	0	0.0	192	59.7

(source of data: Illinois Environmental Protection Agency)

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>