

# Federal Energy Act Report

October 1, 2017 thru September 30, 2018

(Public Record Posted Date: November 19, 2018 )

## General Information:

Total Number of Active UST Facilities: **6,633**  
 Total Number of Active/Inactive USTs: **18,627**

## Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,216**  
 Percent of UST Facilities in SOC Compliance: **63**

### Note:

*Facility and tank information is based on onsite inspections of all active regulated UST facilities and covers all active/inactive tanks at those facilities. Active regulated Illinois UST facilities are inspected on a two year cycle. Onsite inspections measure compliance against Illinois UST requirements at 41 Illinois Administrative Code Parts 174, 175, 176 & 177 and federal UST regulations at 40 CFR Part 280.*

## Summary Information For Releases:

Number of Confirmed UST Releases: **333**

## Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	
Tank	206	61.90	0	0.00	7	2.10	2	0.60	125	37.54	0	0.00	0	0.00	72	21.62
Piping	30	9.00	0	0.00	0	0.00	3	0.90	11	3.30	0	0.00	0	0.00	16	4.80
Dispenser	3	0.90	0	0.00	0	0.00	1	0.30	0	0.00	0	0.00	0	0.00	2	0.60
Submersible (STP)	1	0.30	0	0.00	0	0.00	0	0.00	1	0.30	0	0.00	0	0.00	0	0.00
Delivery Problem	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Unknown	0	27.90	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	93	27.93
Other	93	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Totals	333	100.0	0	0.00	7	2.10	6	1.80	137	41.14	0	0.00	0	0.00	183	54.95

(source of data: Illinois Environmental Protection Agency)

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>